

ENC28J60 Rev. B4 Silicon Errata

The ENC28J60 (Rev. B4) parts you have received conform functionally to the Device Data Sheet (DS39662), except for the anomalies described below. Any data sheet clarification issues related to this device will be reported in a separate data sheet errata. Please check the Microchip web site for any existing issues.

The following silicon errata apply only to ENC28J60 devices with the following revision identifier:

Part Number	Device Revision (EREVID)
ENC28J60	0000 0100

EREVID is located at address 0312h in the device's memory register space.

1. Module: MAC Interface

When the SPI clock from the host microcontroller is run at frequencies of less than 8 MHz, reading or writing to the MAC registers may be unreliable.

Work around

Run SPI at frequencies of at least 8 MHz, or use the same clock source for both ENC28J60 and the host controller for synchronization.

2. Module: Reset

After sending an SPI Reset command, the PHY clock is stopped but the ESTAT.CLKRDY bit is not cleared. Therefore, polling the CLKRDY bit will not work to detect if the PHY is ready.

Additionally, the hardware start-up time of 300 μ s may expire before the device is ready to operate.

Work around

After issuing the Reset command, wait for at least 1 ms in firmware for the device to be ready.

3. Module: Core (Operating Specifications)

The device data sheet specifies that industrial operating temperature range (-40°C to +85°C) is supported. However, this silicon revision only supports the commercial temperature range (0°C to 70°C).

Work around

None at this time.

4. Module: Oscillator (CLKOUT Pin)

No output is available on CLKOUT during Power Save mode (ECON2.PWRSV = 0).

Work around

If the host controller uses the CLKOUT signal as the system clock, do not enable Power Save mode.

5. Module: Memory (Ethernet Buffer)

When the Start Pointer for the Ethernet receive buffer (ERXST) is written to, the Receive Write Pointer (ERXWRPT) is not updated reliably.

Work around

Use the lower segment of the buffer memory for the receive buffer, starting at address 0000h. For example, use the range (0000h to n) for the receive buffer, and ((n + 1) – 8191) for the transmit buffer.

6. Module: Interrupts

The EIR.PKTIF bit may not become set when a packet is pending.

Work around

Check the value of EPKTCNT to see if a packet is pending.

7. Module: PHY

The automatic polarity detection and correction features of the PHY layer do not work as described. This may cause poor receive network performance, or no receive activity, with some link partners.

Work around

When designing the application, always verify that the TPIN+ and TPIN- pins are connected correctly.

8. Module: PHY

The external resistor value recommended for RBIAS in the current data sheet does not apply to this revision of silicon.

Work around

Rev. B4 silicon requires that a 2.7 k Ω , 1% external resistor be attached from the RBIAS pin to ground.

9. Module: PHY

The PHY Half-Duplex Loopback mode, enabled when `PHCON1.PDPXMD = 0`, `PHCON2.HDLDIS = 0`, `PHCON2.FRCLNK = 1` or a link partner is connected, does not loop packets back to itself reliably.

Work around

Perform loopback diagnostics in full duplex using an external loopback connector/cable. To avoid looping occasional packets back to one self, `PHCON2.HDLDIS` should be set by the host controller. `PHCON2.HDLDIS` is clear by default.

10. Module: PHY

The PHY Full-Duplex Loopback mode, enabled when `PHCON1.PDPXMD = 1` and `PHCON1.PLOOPBK = 1`, does not loop packets back to itself reliably.

Work around

Perform loopback diagnostics in full duplex using an external loopback connector/cable.

11. Module: PHY LEDs

When the `PHLCON` register is programmed to output the duplex status and collision activity on the same LED (`1110b`), only the duplex status will be displayed (i.e., the LED will be illuminated when in Full-Duplex mode and extinguished when in Half-Duplex mode, regardless of collision activity).

Work around

When Half-Duplex mode is being used, program the `PHLCON` register's `LxCFG` bits with `'0011b'` to display the collision status. When Full-Duplex mode is being used, program the `PHLCON` register's `LxCFG` bits with `'0101b'` to display the duplex status.

12. Module: Transmit Logic

In Half-Duplex mode, a hardware transmission abort caused by excessive collisions (`MACLCON1`) may stall the internal transmit logic. The next packet transmit initiated by the host controller will never succeed (`ECON1.TXRTS` will remain set indefinitely).

Work around

Before attempting to transmit a packet (setting `ECON1.TXRTS`), reset the internal transmit logic by setting `ECON1.TXRST` and then clearing `ECON1.TXRST`. The host controller may wish to issue this Reset before any packet is transmitted (for simplicity), or it may wish to conditionally reset the internal transmit logic based on the Transmit Error Interrupt Flag (`EIR.TXERIF`), which will become set whenever excessive collisions occur.

13. Module: Memory (Ethernet Buffer)

The receive hardware may corrupt the circular receive buffer (including the Next Packet Pointer and receive status vector fields) when an even value is programmed into the `ERXRDPH:ERXRDPHL` registers.

Work around

Ensure that only odd addresses are written to the `ERXRDPH` registers. Assuming that `ERXND` contains an odd value, many applications can derive a suitable value to write to `ERXRDPH` by subtracting one from the Next Packet Pointer (a value always ensured to be even because of hardware padding) and then compensating for a potential `ERXST` to `ERXND` wraparound. Assuming that the receive buffer area does not span the `1FFFh` to `0000h` memory boundary, the logic in Example 1 will ensure that `ERXRDPH` is programmed with an odd value:

EXAMPLE 1:

```
if (Next Packet Pointer - 1 < ERXST) or  
(Next Packet Pointer - 1 > ERXND)
```

```
then:
```

```
ERXRDPH = ERXND
```

```
else:
```

```
ERXRDPH = Next Packet Pointer - 1
```

14. Module: MAC

The MAC Loopback mode, enabled when `MACON1.LOOPBK = 1`, does not loop packets back to itself reliably.

Work around

Perform loopback diagnostics in full duplex using an external loopback connector/cable.

Ethernet Conformance Issues

In testing the ENC28J60 device (Revision B4 silicon) for compliance with IEEE Standard 802.3, the following conformance issues have been noted. All of these will be addressed in future revisions of the ENC28J60 silicon.

1. Issue: TP_IDL Pattern

The observed TP_IDL pattern transmitted by ENC28J60 was observed to not stay within the standard defined template when using the TPM (Twisted Pair Model) and TP Test Load 2.

Reference: IEEE Std 802.3, §14.3.1.2.1, Figures 14-10 and 14-11

Potential Application Impact

The TP_IDL test requires a total of six separate sub tests, using three different test loads with and without TPM. The fact that the device consistently passed five of the six sub tests, while narrowly missing the sixth, leads to the conclusion that this is a minor issue. No failures have been observed due to this issue.

Work around

None.

2. Issue: Exiting Link Test Fail State

The ENC28J60 was observed to improperly accept a frame with no preceding LTPs (Link Test Pulse). When a device is in the Link Test Fail state, it should exit this state when a valid packet is received, however, the first packet should not be accepted. The second and subsequent packets should be accepted while the device is in the Link Test Pass state.

Reference: IEEE Std 802.3, Figure 14-6

Potential Application Impact

Link Test Pulse is an integral part of every 10Base-T system. It is used to notify a link partner of the presence of a 10Base-T device. An absence of LTPs signifies that the Ethernet cable is not connected or a link partner is missing. Even when a cable is not connected, a 10Base-T device would continuously send out LTPs. This fact makes it unlikely that there will ever be a situation in which a device would be receiving valid Ethernet frames without already being in the Link Test Pass state.

In the unlikely event that this situation does occur, higher layer protocols would protect the system from accepting unwanted data. It is unlikely that this failure will have significant impact on a networked application. No failures have been observed due to this issue.

Work around

None.

3. Issue: Collision Handling

The delay from the collision event to collision enforcement with the jam pattern is approximately 50 BT (bit times), which is greater than the specified limit of 36 BT.

Reference: IEEE Std 802.3, Annex B, § B.1.2

Potential Application Impact

A collision in a half-duplex 10Base-T is not an unexpected event. It exists as a normal part of the network operation. The purpose of the jam pattern is to ensure that the duration of the collision is sufficient to be noticed by the other transmitting station(s) involved in the collision. A longer delay between the collision event and the start of jam pattern would cause the duration of the collision to be longer.

After each collision, both transmitting stations would back off and wait a random amount of time before attempting to transmit again. The minimum Idle time between each Ethernet frame is 9.6 μ s. The longer collision duration of 14 BT, or 1.4 μ s, can be considered as a small fraction of time wasted for each collision. It is unlikely that this issue will have significant impact on networked applications. No failures have been observed due to this issue.

Work around

None.

ENC28J60

REVISION HISTORY

Rev A Document (2/2006)

Original revision. Silicon errata issues 1 (MAC Interface), 2 (Reset), 3 (Core), 4 (Oscillator), 5 (Memory), 6 (Interrupts), 7-10 (PHY), 11 (PHY LEDs), 12 (Transmit Logic), 13 (Memory – Ethernet Buffer) and 14 (MAC), and Ethernet Conformance issues 1 (TP_IDL Pattern), 2 (Exiting Link Test Fail State) and 3 (Collision Handling).

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELOQ, microID, MPLAB, PIC, PICmicro, PICSTART, PRO MATE, PowerSmart, rPIC, and SmartShunt are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.


AmpLab, FilterLab, Migratable Memory, MXDEV, MXLAB, PICMASTER, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, dsPICDEM, dsPICDEM.net, dsPICworks, ECAN, ECONOMONITOR, FanSense, FlexROM, fuzzyLAB, In-Circuit Serial Programming, ICSP, ICEPIC, Linear Active Thermistor, MPASM, MPLIB, MPLINK, MPSIM, PICkit, PICDEM, PICDEM.net, PICLAB, PICtail, PowerCal, PowerInfo, PowerMate, PowerTool, Real ICE, rLAB, rPICDEM, Select Mode, Smart Serial, SmartTel, Total Endurance, UNI/O, WiperLock and Zena are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2006, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

**QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
== ISO/TS 16949:2002 ==**

Microchip received ISO/TS-16949:2002 quality system certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona and Mountain View, California in October 2003. The Company's quality system processes and procedures are for its PICmicro® 8-bit MCUs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



WORLDWIDE SALES AND SERVICE

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://support.microchip.com>
Web Address:
www.microchip.com

Atlanta
Alpharetta, GA
Tel: 770-640-0034
Fax: 770-640-0307

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Farmington Hills, MI
Tel: 248-538-2250
Fax: 248-538-2260

Kokomo
Kokomo, IN
Tel: 765-864-8360
Fax: 765-864-8387

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

San Jose
Mountain View, CA
Tel: 650-215-1444
Fax: 650-961-0286

Toronto
Mississauga, Ontario,
Canada
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Australia - Sydney
Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing
Tel: 86-10-8528-2100
Fax: 86-10-8528-2104

China - Chengdu
Tel: 86-28-8676-6200
Fax: 86-28-8676-6599

China - Fuzhou
Tel: 86-591-8750-3506
Fax: 86-591-8750-3521

China - Hong Kong SAR
Tel: 852-2401-1200
Fax: 852-2401-3431

China - Qingdao
Tel: 86-532-8502-7355
Fax: 86-532-8502-7205

China - Shanghai
Tel: 86-21-5407-5533
Fax: 86-21-5407-5066

China - Shenyang
Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen
Tel: 86-755-8203-2660
Fax: 86-755-8203-1760

China - Shunde
Tel: 86-757-2839-5507
Fax: 86-757-2839-5571

China - Wuhan
Tel: 86-27-5980-5300
Fax: 86-27-5980-5118

China - Xian
Tel: 86-29-8833-7250
Fax: 86-29-8833-7256

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-2229-0061
Fax: 91-80-2229-0062

India - New Delhi
Tel: 91-11-5160-8631
Fax: 91-11-5160-8632

India - Pune
Tel: 91-20-2566-1512
Fax: 91-20-2566-1513

Japan - Yokohama
Tel: 81-45-471-6166
Fax: 81-45-471-6122

Korea - Gumi
Tel: 82-54-473-4301
Fax: 82-54-473-4302

Korea - Seoul
Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Penang
Tel: 60-4-646-8870
Fax: 60-4-646-5086

Philippines - Manila
Tel: 63-2-634-9065
Fax: 63-2-634-9069

Singapore
Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Hsin Chu
Tel: 886-3-572-9526
Fax: 886-3-572-6459

Taiwan - Kaohsiung
Tel: 886-7-536-4818
Fax: 886-7-536-4803

Taiwan - Taipei
Tel: 886-2-2500-6610
Fax: 886-2-2508-0102

Thailand - Bangkok
Tel: 66-2-694-1351
Fax: 66-2-694-1350

EUROPE

Austria - Wels
Tel: 43-7242-2244-399
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4450-2828
Fax: 45-4485-2829

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

UK - Wokingham
Tel: 44-118-921-5869
Fax: 44-118-921-5820